$\vdash$	Type	# 1	Hits	Search Text	DBs	Time Stamp Co	Comments	Error Definition	rs
1		1.2	531	Ll and chip	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/10/11 22:11			0
<del>                                     </del>	BRS	1.1	636	257/738.ccls.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/10/11 22:25			0
m	IS&R	Г3	1	("5517058").PN.	USPAT	2001/10/11 22:27			0
4	BRS	L4	93	257/795.ccls.	USPAT	2001/10/11 22:33			0
2	BRS	1.5	513	257/784.ccls.	USPAT	2001/10/11 22:35			0
9	BRS	T-6	326	L5 and lead	USPAT	2001/10/11 22:41			0
7	BRS	L7	319	257/785.ccls.	USPAT	2001/10/11 22:50			0
8	IS&R	L8	0	<pre>("((elastic or poly\$) near (lead or contact)) and ( circuit adj board)").PN.</pre>	USPAT	2001/10/11 22:51			0
6	BRS	1.9	306	((elastic or poly\$) near (lead or contact)) and (circuit adj board)	USPAT	2001/10/11 23:02		Ituncacion Overrom Return string from Server is: 5.180097	г
10	BRS	L10	2377	((elast\$ or poly\$) near (lead or contactor conduct\$)) and (( circuit adj board) or substrate or chib)	USPAT	2001/10/11 23:24		Truncation Overflow. Return string from Server is: 5.0.0 EIA	П
11	BRS	L11	2332	L10 not L9	USPAT	2001/10/11 23:05			0
12	BRS	L12	401	257/\$ and L11	USPAT	2001/10/11 23:08		Truncation Overflow. Return string from Server is: 5.0.0.257	н
13	BRS	L13	4612	((elast\$ or poly\$) near (lead or contactor conduct\$))	USPAT	2001/10/11 23:26		Truncation Overflow. Return string from Server is: 5.0.0 ELA	
14	BRS	L14	293	L13 and 257/\$.ccls.	USPAT	2001/10/11 23:26			0
15	BRS	115	293	257/\$.ccls. and L13	USPAT	2001/10/11 23:27			0
16	BRS	L16	424	257/\$ and L13	USPAT	2001/10/11 23:28		Truncation Overflow. Return string from Server is:	Н
17	BRS	117	293	L15 or L14	USPAT	2001/10/11 23:28			0
18	BRS	L18	431	L15 or L16	USPAT	2001/10/11 23:28			0
19	BRS	L19	30	L18 not L12	USPAT	2001/10/11 23:29			٥